





September, 2017

ERRATUM

Page	Position	Error	Correct
7	5 Table 4 c)	 <p>Diagram illustrating the error in the fastening method. The error is shown as the distance from the center of the taper hole (ϕD_1) to the outer edge of the hub, indicated by dimension lines $\phi D_5 / \phi D_3$ and ϕD_4.</p>	 <p>Diagram illustrating the corrected fastening method. The corrected position is indicated by dashed lines, showing the distance from the center of the taper hole (ϕD_1) to the outer edge of the hub, indicated by dimension lines $\phi D_5 / \phi D_3$ and ϕD_4.</p>
11	Table 6 c)	 <p>Diagram illustrating the error in the fastening method. The error is shown as the distance from the center of the spherical seat (ϕD_1) to the outer edge of the hub, indicated by dimension lines $\phi D_3 / \phi D_3$ and ϕD_4.</p>	 <p>Diagram illustrating the corrected fastening method. The corrected position is indicated by dashed lines, showing the distance from the center of the spherical seat (ϕD_1) to the outer edge of the hub, indicated by dimension lines $\phi D_3 / \phi D_3$ and ϕD_4.</p> <p>(: Corrected position)</p>

NOTE: The second edition of the English version published in and after September, 2017 will include the content of this erratum.